1° 6 $\frac{1}{4}$ E. (a.) Light.—Details: The revolving white light has been replaced by a flashing white light every thirty seconds, vis. 10 miles, showing thus, flash $1\frac{1}{2}$ secs., eclipse $28\frac{1}{2}$ secs. Remarks: The lantern is at the masthead, and will serve as $E = 28\frac{1}{2}$ secs. Sumarka, South Coast. a daymark in lieu of the former ball; the other details remain unchanged.

MEDITERRANEAN.----EGYPT.

Suez Canal.—Intended Increase in Maximum Draught SUEZ CANAL.—INTENDED INCREASE IN MAXIMUM DRAUGHT OF VESSELS PASSING THROUGH.—Date: On and after 1st January, 1915. Position: Port Said, lat. 31° 16' N., long. 32° 19' E. Details: On and after the above date, the maxi-mum draught of vessels passing through the Suez Canal will be increased to 30 ft. Remarks: The following note has been inserted on Charts Nos. 3214 and 234, and the two notes on Chart No. 233 corrected accordingly—"Vessels of 29 ft. draught are permitted to pass through the canal; this will be increased to 30 ft. in January, 1915."

FORMOSA, WEST COAST .-- PESCADORES CHANNEL.

ONKAN TAI (WANKAN BANK) .--- LIGHT ESTABLISHED.-ONKAN 'TAI (WANKAN BANK).—LIGHT ESTABLISHED.— Position: On Pinboisoa Sandbank, at a distance of about one mile from its northern end. Lat. 23° 31' 30" N., long. 120° 2' 2" E., on Chart No. 2409. Details: Character—a flashing white light every two seconds. Elevation — 58 ft. Visibility—13 miles. Power—800 candles. Structure—black framework, 50 ft. in height to centre of lantern. Remarks: The light is unverticed The light is unwatched.

INDIA, WEST COAST.

SCAPE MONZE (RAS MUARI).—LIGHT ESTABLISHED.—Posi-tion: On the low land of the cape about a mile to the south-castward of the north-west extreme. Lat. 24° 49′ 40″ N., long. 66° 39′ 55″ E., on Chart No. 41. Details: Character—a group flashing white light showing a group of two flashes every ten seconds, thus, flash, 0.3 sec., eclipse, 2.5 secs.; flash, 0.3 sec., oclipse, 6.9 secs. Elevation— 150 ft. Visibility—18 miles, from 277° (N. 85° W. mag), through north, to 138° (S. 44° E. mag.). Order—1st. Struc-ture—a concrete tower painted with black and white bands. Note: The note "Lt. Ho. established 1914, not shown" has been inserted below Cape Monze in the view on Chart No. 41. Variation: 2° E. Variation : 2° E.

ARGENTINA.

BUENOS AIRES .- DETAILS OF WIRELESS TIME-SIGNAL. Position : North Basin Signal-station, lat. 34° 35½ S., long. 58° 22′ W. Details : This station transmits wireless time-signals at 23 h. 56 m., 23 h. 58 m., and 0 h. 0 m., Cordova mean time, corresponding to 4 h. 12 m. 48.2 s., 4 h. 14 m. 48.2 s., and 4 h. 16 m. 48.2 s. Greenwich mean time respectively, thus :

н.	М.	s. н.	М.	s.	
23	55	00 to 23	55	50	&c.
23	56	00			
23	57	00 to 23	57	50	&c.
	58				-
23	59	00 to 23	59	50	&c.
00	00	00			-

MEXICO, PACIFIC COAST.

LIGHTS EXTINGUISHED .- Details : All lights on the Pacific Coast of Mexico have been extinguished.

CENTRAL AMERICA, WEST COAST.-NICARAGUA.

CORINTO HARBOUR, CARDON ISLAND.—ALTERATION IN CHARACTERISTICS OF LIGHT.—Position: On Cardon Head. Lat. 12° 28' N., long. 87° 12½' W. Details: The fixed white light has been replaced by a light having the undermentioned characteristics: Character—a flashing white light every three seconds, showing thus, flash 0.3 sec., eclipse 0.7 sec. Eleva-tion—87 ft. Visibility—14 miles. Power—1,010 candles. Remarks: The light is unwatched. "Unreliable," formerly shown against this light on the charts, has been expunged; the other details remain unchanged.

ENGLAND, SOUTH COAST .- PORTSMOUTH APPROACH.

OWERS LIGHT-VESSEL .- FURTHER DETAILS WITH REGARD OWERS LIGHT-VESSEL.—FURTHER DETAILS WITH REGARD TO WRECK SOUTHWARD OF.—*Position*: At a distance of $1\frac{1}{2}$ miles, 170° (S. 5° W. mag.), from Owers light-vessel. Lat. 50° 35³/₄ N., long. 0° 40¹/₂ W. *Description*: Wreck of s.s. "Carbineer," over which there is a least depth of 10 fa-thoms. *Remarks*: A depth of 10 fathoms surrounded by a danger line, and marked "Wreck (1914) (position approxi-mate)," has been placed on the charts in the above position.

CHINA, SOUTH-EAST COAST.

HONGKONG HARBOUR .--- EXTENSION OF COALING CAMBER. -Position : Coaling camber, lat. 22° 184' N., long. 114° 10' E.

TELOK BETONG.—LIGHT TO BE DISCONTINUED.—Date of discontinuance: 1st July, 1914. Position: At a distance of about 440 yards, north-castward from the new pier. Lat. 5° 27' S., long. 105° 164' E. Description: A flashing white light. Remarks: The light has been expunged from the charts. Note: No further notice will be given.

BBITISH COLUMBIA.

STRAIT OF GEORGIA.—ACTIVE PASS.—GOSSIP SHOALS.— SUBMARINE BELL-BUOY ESTABLISHED.—Notice is given that a submarine bell-buoy, painted black, has been established 200 ft. 193° from Gossip Shoals bell-buoy, Active Pass, Strait of Georgia, British Columbia.

The buoy is cylindrical in shape and the submarine bell is actuated by the motion of the buoy on the waves

Approx. position : Lat. 48° 53' 20" N., long. 123° 18' 16" W.

BURRARD INLET. --- SPANISH BANK. --- SUBMARINE BELL-BUOY ESTABLISHED.—Notice is given that a submarine bell-buoy, painted red, has been established 200 ft. 85° from Grey Point gas and bell buoy, off Spanish Back, entrance to Burrard Inlet, Strait of Georgia, British Columbia.

The buoy is cylindrical in shape and the submarine bell is actuated by the motion of the buoy on the waves

Approx. position : Lat. 49° 17' 15" N., long. 123° 15' W.

VANCOUVER HARBOUR.—BURNABY SHOAL.—LIGHT AND FOG-BELL ESTABLISHED. — FLOAT DISCONTINUED. — A red wooden platform beacon, supported on wooden piles and surmounted by a steel tripod carrying a light and fog-bell, has been established in 15 ft. of water on Burnaby Shoal, Vancouver Harbour, British Columbia, on the bearings—

Wesleyan Church		••		208° 00'
Foot of Bute Street	••	••	••	
Burkton Point	••	• •	• •	$306^{\circ} 50'$
Prospect Point	••	••	• •	309° 00′

The light is an unwatched fixed red incandescent electric light.

The fog-bell is operated by electricity, and sounds 2 strokes in quick succession every 5 seconds.

The wooden platform buoy carrying a light and fog-bell, heretofore moored on the eastern edge of Burnaby Shoal, has been withdrawn.

VANCOUVER ISLAND. — EAST COAST. — SIDNEY, — LIGHT ESTABLISHED.—A 6th-order *fixed red* electric light of 100 candle-power has been established on the north-eastern end of the Government Wharf at Sidney, east coast of Vancouver Island.

The light is exhibited from a pole. Approx. position: Lat. 48° 38′ 55″ N., long. 123° 23′ 28″ W.

SOUTH-WEST COAST.—OBSTRUCTION ISLAND.—ROCKY PASS -BEACON ESTABLISHED.-The Canadian Government has given notice that a white beacon 18 ft. high, consisting of a square concrete base surmounted by a staff carrying a square wooden slat-work target, has been erected on the rock in the middle of Rocky Pass, Obstruction Island, south-west coast of Vancouver Island.

Approx. position : Lat. 49° 23' 10" N., long. 126° 6' 9" E.

H.O. Charts Nos. 527, 903, 1450, and 1597.

H.O. Publication No. 96, The Coast of British Columbia, 1907, page 407.

STRAIT OF GEORGIA.—NANAIMO HARBOUR APPROACH.— SNAKE ISLAND REEF.—BELL-BUOY REPLACED.—Referring to Notice to Mariners No. 23 (1855) of 1914, the Canadian Government has given further notice that the bell-buoy marking the southern end of the reef, southward of Snake Island, Nanaimo Harbour approach, British Columbia, which was carried away by the sea has been replaced in position was carried away by the sea, has been replaced in position.

Approx. position: Lat. 49° 12' 14" N., long. 123° 53' 2" W.

VANCOUVER ISLAND. - SAANICH INLET. - WHITE ROCKS. BUOY ESTABLISHED .- A black wooden spar buoy has been established about 600 yards south-westward of White Rocks, Saanich Inlet, Vancouver Island, British Columbia. The following sextant angles fix the position of the buox :----

The following sexua	int angles nx	the post	tion of	the buoy :
Hatch Point	••		•••	0° 00′
Coal Point	••	••		22° 30′
White Rocks	••	••	••	47° 00′
Approx. position :	Lat. 48° 37'	20″ N., l	ong. 12	3° 29′ 5″ W.