Notice to Mariners No. 55 of 1926.

NEW ZEALAND .- NORTH ISLAND .- WEST COAST .- MANUKAU HARBOUR ENTRANCE.

> Marine Department, Wellington, N.Z., 6th October, 1926.

1. Paratutai : Light to be installed.

3.

Windy Point: Unlighted beacons realigned. Main lighted leading beacons : Amended transit. Destruction Gully : Light to be discontinued. Destruction Gully : White Patch to be obliterated. 4. 5.

Directions for entering. 6.

THE Auckland Harbour Board notify that, owing to recent alterations in the channels and banks at the entrance to Manukau Harbour, the undermentioned changes in naviga-tional "aids" will take place, and will come into operation on and after the evening of Monday, 1st November, 1926 :---

1. Paratutai Light (Unwatched).—A flashing light, having red, white, and green sectors, 12 seconds, flash 4 seconds, 25 ft., visible 8 miles, will be exhibited from the extreme southern end of Paratutai. The light shows red from 237° to 253°, white thence to 261°, green thence to 050°, white thence to 057°, red thence to 077°, obscured elsewhere. Position: From Paratutai light, South Head Signal-station and the paratula is the sector Head Light in the second state.

flagstaff bears $095\frac{1}{2}^{\circ}$, and South Head Lighthouse 116°.

2. Windy Point Unlighted Beacons .- Two white beacons, at Pigeonhole, northward of the entrance, have been realigned for use as day marks only, and will be in transit 032¹/₂°.

3. Main Lighted Leading Beacons.—Amending Wellington Notice to Mariners No. 36 of 1926, the alignment of these beacons at South Head in transit is $069\frac{1}{2}^{\circ}$.

4. Destruction Gully Light .- This light, at the northern side within the entrance, will be discontinued.

5. Destruction Gully White Patch .- This white patch, at the northern side within the entrance, is to be obliterated.

6. Directions for Entering.—During night-time: Vessels should cross the main bar with the main leading-beacon lights at South Head in transit $069\frac{1}{2}^\circ$, continuing until well within the white sector of Paratutai light; thence altering course to pass Paratutai light, keeping within the white sector of that light until approaching Paratutai as closely as may be neces-

During daytime : Vessels should cross the main bar with During daytime: Vessels should cross the main bar with the main leading-beacons in transit $069\frac{1}{2}^\circ$, continuing until Windy Point beacons are in transit $032\frac{1}{2}^\circ$; thence altering course to pass Paratutai. The signal-station should be kept under close observation, and any directional instructions given by semaphore or otherwise should be promptly com-plied with.

Publications affected: Admiralty Plan No. 2626, Charts Nos. 2535 and 2543; "New Zealand Pilot," 9th edition, 1919; page 66 et seq.; "New Zealand Nautical Almanac," 1926, page 290 et seq. and plan facing page 294; Admiralty List of Lights, Part 6, 1924, Nos. 2986, 2988, and 2990.

G. C. GODFREY, Secretary.

Notice to Mariners .- No. 56 of 1926.

Marine Department, Wellington, N.Z., 6th October, 1926. THE following is a copy of a Notice to Mariners which has been received from the Comptroller of Customs, Suva, and is published for general information.

G. C. GODFREY, Secretary.

His Majesty's Customs, Suva, 13th August, 1926.

NOTICE TO MARINERS.

H.M.S. "Veronica" reports having located a shoal having a radius of 50 yards and a least depth of 4 fathoms in latitude 17° 47' 26" south and longitude 177° 16' 24" east, bearing $115\frac{1}{2}$ degrees from Vatumbula Island, and distant therefrom 3.2 miles.

M.P. 3661/26.

E. J. MARCH, Comptroller of Customs.

Notice to Mariners No. 57 of 1926.

NEW ZEALAND .- NORTH ISLAND .- NORTHERN COAST .- AUCK-LAND HARBOUR.

Marine Department, Wellington, N.Z., 12th October, 1926.

Dredger operating off Sheerlegs Wharf.

THE Auckland Harbour Board notify that the dredger "Hapai" is operating in the vicinity and southward and south-eastward of the new extension to Sheerlegs Wharf, Care must be observed to avoid the dredger's Devonport.

Devonport. Care must be observed to avoid the dreagers moorings which are laid cardinally. Publications affected : Admiralty Plan No. 1970; "New Zealand Pilot," 9th edition, 1919, pages 192 and 197; "New Zealand Nautical Almanac," 1926, pages 240 and 245; "New Zealand Nautical Almanac," 1927, page 222.

G. C. GODFREY, Secretary.

Branch of Friendly Society registered.

Freindly Societies Department, Wellington, 5th October, 1926. THE Court Pride of Kaukapakapa, No. 9869, situated at Kaukapakapa, is registered as a branch of the Auckland District Branch of the Ancient Order of Foresters of New Zealand Friendly Society No. 356, under the Friendly Societies Act, 1909, this 5th day of October, 1926.

WILLIAM M. WRIGHT, Registrar of Friendly Societies.

CROWN LANDS NOTICES.

Lands in the Gisborne Land District forfeited.

Department of Lands and Survey, Wellington, 30th September, 1926. N OTICE is hereby given that the licenses of the undermentioned lands having been declared forfeited by resolution of the Giaborne Land Board the said lands have thereby provided to the Grame and the said lands have the

IN the Gisborne Land Board, the said lands have thereby reverted to the Crown, under the provisions of the Land Act, 1924, and the Discharged Soldiers Settlement Act, 1915, and amendments.

SCHED	TILE
DOLLED	ULLI.

GISBORNE LAND DISTRICT.

Tenure.	Lease No.	Section.	Block.	District.	Licensee.	Reason for Forfeiture.
O.R.P.	3278	7	XV	Waioeka Survey District	L. R. and S. H. Williams	Non-compliance with conditions of license.
"	3282	2	III	Waioeka South Survey District	. , , , , , , , , , , , , , , , , , , ,	Ditto.
,,	3285	1	XVI	Waiawa Survey District	A. Tuke	
,,	5416	4	VIII	Urutawa Survey District		At request.
,,	4023	193		Waiotahi Parish	J. P. Morine	
"	5534	1	VI	Opotiki Survey District	C. W. Reid	Non-compliance with conditions of license.

K. S. WILLIAMS, for Minister of Lands.

2942