

DIAGRAM 7. (Table 18.)

*Method of Measuring Circumference of Wire Rope.*—The circumference of a wire rope shall be measured at three places at least five ft. apart, with a suitable device such as a rope caliper as shown in the diagram. The average of these measurements shall be the circumference of the rope.




DIAGRAM 8.