Schedule 2.—Builders' Ironmongery—continued.

|   | Description.  |  |  |                           |                                 |                   | Rate.  | At per                            | Contractor.   |   |
|---|---|--|--|---------------------------|---------------------------------|-------------------|--|-----------------------------------|---|---|
| 256   | Latches, gate, sp<br>Latches, gate, co  |  |  |                           |                                 |                   | 8/6  | doz.                              | Walter Scott  | , Greymouth.                            |
| 257   | Japanned in   |  | p.   |                           |                                 |                   | 5/   |                                   | ,,  | "                                       |
| 258   | Galvanized  |  |  |                           |                                 |                   | 5/6  | ,,                                | ,,  |   |
| 266   | Lifts, sash, hook   |  | s. Cartlan   | d's No. 7                 | '434, 2 <del>1</del> ir         |                   | 3/6  | ,,                                | ,,  | ,,                                      |
| 267   | Lifts, sash, ring,  |  |  |                           |                                 |                   | 4/   | ,,                                | ,,  |   |
|   | Locks, cupboard   |  |  |                           | ~-,1                            |                   | -/   | ,,                                | ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,                 | ,,                                      |
| 273   | $2\frac{1}{2}$ in.  | ,  |  |                           |                                 |                   | 60/  | ,,                                | ,,  | ,,                                      |
| 274   | 3 in  |  |  |                           |                                 |                   | 60/  | ,,                                | ,,  | ,,                                      |
| 276   | Locks, cupboard   |  |  |                           |                                 |                   | 64/  | ,,                                | ,,  | , ,,                                    |
|   | Locks, till, 4-lev  |  |  |                           | ,                               |                   | -,-/   | ,,                                | /"  |   |
| 278   | 2 in  |  |  |                           |                                 |                   | 48/  | ,,                                | ,,  | ,,                                      |
| 280   | $2\frac{3}{4}$ in.  |  |  | , ,                       |                                 |                   | 48/  |                                   |   |   |
| 281   | 3 in  | • • •  |  |                           |                                 |                   | 51/  | ,,                                | ,,  | ,,                                      |
| 282   | Locks, till, Yale   |  |  |                           |                                 | :                 | 48/  | ,,                                | ,,,   | ,,                                      |
| 295   | Locks, Miller Locks   |  |  |                           |                                 |                   | 30/  | ,,                                | ,,  | , ,,                                    |
| 290   | No. 1   | JCK CO   | ицрацу в   | Champ                     | 1011, U -                       | level,            | 307  | ,,                                | "   | ,,                                      |
|   | Locks, rim, 2-bolt, Vaughan's No. 60 (push-in bolts)—   |  |  |                           |                                 |                   |  |                                   |   |   |
| 301   | 6 in  |  | ngnan s r  | ю. 60 (р                  | den-m no                        | 168)              | 4E /   |                                   | Forgyth and   | Makar Cres                              |
| 301   | о щ   | • •  | • •  | • •                       | • •                             | • •               | 45/  | ,,                                | Forsyth and mouth.                                      | mckay, Grey                             |
| 909   | <b>-</b>  |  |  |                           |                                 |                   | PF /   |                                   |   |   |
| 302   | 7 in  | • •  | • •  | •• .                      | • •                             |                   | 55/  | ,,                                | Ditto.  |   |
| 900   | NT '1 1 4   |  |  |                           |                                 |                   | 1 /10  | 11                                | W-14 C 44   | G (1                                    |
| 306   | Nails, slate, copp  |  |  |                           |                                 |                   | 1/10   | lb.                               | Walter Scott,   | , Greymouth.                            |
| 313   | Openers, fanligh  |  |  |                           |                                 | stem,             | 7/6  | $\mathbf{each}$                   | "   | ,,                                      |
|   | " Convertibl  | e,'' all   | brass, Ca  | irtland's                 | No. 1795                        |                   | İ  |                                   |   |   |
| 319   | Plates, finger (ebony, cocus, or oak), long-reeded, approved pattern Plugs and washers, cast—   |  |  |                           |                                 |                   | 2/6  | pair                              | Forsyth and McKay, Grey mouth.                          |   |
|   | ~ ~   |  | it—  | ·                         | O                               | ~, - <sub>T</sub> | 2/0  | pan                               |   | izozzaj, Groj                           |
|   | Plugs and washe   |  | t—   |                           | ·O                              | -, -r             | 2/0  | pan                               |   | izozady, orzoy                          |
| 320   | Plugs and washe<br>Round—   |  | t  |                           |                                 | _                 | ,  |                                   | mouth.  |   |
| <b>32</b> 0   | Plugs and washe<br>Round—<br>2 in   |  | ·•t—   |                           |                                 | · · ·             | 1/   | each                              |   |   |
|   | Plugs and washe<br>Round—<br>2 in<br>Square—  | ers, cas   | ••   | •                         |                                 | •••               | 1/   | each                              | mouth.  Walter Scott                                    | , Greymouth.                            |
| 322   | Plugs and washe<br>Round—<br>2 in<br>Square—<br>2 in  | ers, cas   | <br>   | ••                        |                                 | _                 | 1/   | each ,,                           | mouth.  Walter Scott,                                   | , Greymouth.                            |
|   | Plugs and washed Round—  2 in   | ers, cas   | •••  |                           |                                 | • •               | 1/   | each                              | mouth.  Walter Scott                                    | , Greymouth.                            |
| 322   | Plugs and washe Round— 2 in Square— 2 in 2½ in. Pulleys, axle,  | ers, cas   | •••  |                           |                                 | •••               | 1/   | each ,,                           | mouth.  Walter Scott,                                   | , Greymouth.                            |
| 322<br>323  | Plugs and washe Round— 2 in Square— 2 in 2½ in. Pulleys, axle, Kenrick's-   | ers, cas   | •••  |                           |                                 | • •               | 1/<br>1/3<br>1/7   | each                              | mouth.  Walter Scott,                                   | , Greymouth.                            |
| 322<br>323<br>329   | Plugs and washe Round— 2 in Square— 2 in 2½ in. Pulleys, axle, Kenrick's- 1¾ in.  | ers, cas   | •••  |                           |                                 | <br>heels,        | 1/<br>1/3<br>1/7   | each ,, ,, doz.                   | mouth.  Walter Scott,                                   | Greymouth.                              |
| 322<br>323  | Plugs and washe Round— 2 in Square— 2 in 2½ in. Pulleys, axle, Kenrick's- 1¾ in. 2 in   | ers, cas   | <br><br>brass<br>  | <br>face,<br>             | <br>iron w                      | <br>heels,        | 1/<br>1/3<br>1/7   | each                              | mouth.  Walter Scott,                                   | , Greymouth.                            |
| 322<br>323<br>329<br>330  | Plugs and washed Round—  2 in Square—  2 in 2½ in.  Pulleys, axle, Kenrick's— 1¾ in. 2 in Quadrants, iron,  | ers, cas   | <br><br>brass<br>  | <br>face,<br>             | <br>iron w                      | heels,            | 1/<br>1/3<br>1/7<br>3/9<br>5/  | each ,, ,, doz.                   | mouth.  Walter Scott,                                   | Greymouth.                              |
| 322<br>323<br>329<br>330<br>335   | Plugs and washe Round— 2 in Square— 2 in 2½ in. Pulleys, axle, Kenrick's- ½ in. 2 in Quadrants, iron, 16 in.  | ers, cas   | <br><br>brass<br>  | <br>face,<br>             | <br>iron w                      | <br>heels,<br>    | 1/<br>1/3<br>1/7<br>3/9<br>5/<br>2/3   | each ,, ,, doz. ,, each           | mouth.  Walter Scott,                                   | Greymouth.                              |
| 322<br>323<br>329<br>330  | Plugs and washed Round— 2 in Square— 2 in 2½ in. Pulleys, axle, Kenrick's— 1¾ in. 2 in Quadrants, iron, 16 in. 18 in.   | secret, Beanla   | <br>, brass<br><br>and's, Car                                    | face, tland's M           | <br>iron w<br><br><br>Vo. 9052— | <br>heels,<br>    | 1/<br>1/3<br>1/7<br>3/9<br>5/  | each ,, ,, doz.                   | mouth.  Walter Scott,                                   | Greymouth.                              |
| 322<br>323<br>329<br>330<br>335   | Plugs and washe Round— 2 in Square— 2 in 2½ in. Pulleys, axle, Kenrick's- 1¾ in. 2 in Quadrants, iron, 16 in. 18 in. Screws, wood, 6  | secret,  Beanla  | brass and's, Car Keen, and                                       | face, tland's M           | <br>iron w<br><br><br>Vo. 9052— | <br>heels,<br>    | 1/<br>1/3<br>1/7<br>3/9<br>5/<br>2/3   | each ,, ,, doz. ,, each           | mouth.  Walter Scott,                                   | Greymouth.                              |
| 322<br>323<br>329<br>330<br>335   | Plugs and washe Round— 2 in Square— 2 in 2½ in. Pulleys, axle, Kenrick's- 1¾ in. 2 in Quadrants, iron, 16 in. 18 in. Screws, wood, G off current to   | secret,  Beanla  | brass and's, Car Keen, and                                       | face, tland's 1           | <br>iron w<br><br><br>Vo. 9052— | <br>heels,<br>    | 1/<br>1/3<br>1/7<br>3/9<br>5/<br>2/3   | each ,, ,, doz. ,, each           | mouth.  Walter Scott,                                   | Greymouth.                              |
| 322<br>323<br>329<br>330<br>335<br>336                                    | Plugs and washed Round—  2 in Square—  2 in 2½ in. Pulleys, axle, Kenrick's— 1¾ in. 2 in Quadrants, iron, 16 in. 18 in. Screws, wood, Goff current to   | secret, Beanla   | brass  and's, Car Keen, and                                      | face, tland's 1           | <br>iron w<br><br><br>Vo. 9052— | heels,            | 1/<br>1/3<br>1/7<br>3/9<br>5/<br>2/3<br>2/3  | each  ,,  doz.  ,,  each ,,       | mouth.  Walter Scott,                                   | Greymouth.                              |
| 322<br>323<br>329<br>330<br>335<br>336                                    | Plugs and washe Round— 2 in Square— 2 in 2½ in. Pulleys, axle, Kenrick's- 1¾ in. 2 in Quadrants, iron, 16 in. 18 in. Screws, wood, G off current to Iron— Countersunk   | secret, Beanla   | brass  and's, Car Keen, and                                      | face,tland's N l Nettlef  | <br>iron w<br><br><br>Vo. 9052— | heels,            | 1/<br>1/3<br>1/7<br>3/9<br>5/<br>2/3<br>2/3  | each  doz.  each  per cent.       | mouth.  Walter Scott,                                   | Greymouth.                              |
| 322<br>323<br>329<br>330<br>335<br>336                                    | Plugs and washed Round—  2 in Square—  2 in 2½ in. Pulleys, axle, Kenrick's- 1¾ in. 2 in Quadrants, iron, 16 in. 18 in. Screws, wood, Goff current of Iron— Countersunk Round head  | secret, Beanla   | brass  and's, Car Keen, and                                      | face, tland's 1           | <br>iron w<br><br><br>Vo. 9052— | heels,            | 1/<br>1/3<br>1/7<br>3/9<br>5/<br>2/3<br>2/3  | each  ,,  doz.  ,,  each ,,       | mouth.  Walter Scott,                                   | Greymouth. " " " " " "                  |
| 322<br>323<br>329<br>330<br>335<br>336                                    | Plugs and washe Round— 2 in Square— 2 in 2½ in. Pulleys, axle, Kenrick's- 1¾ in. 2 in Quadrants, iron, 16 in. 18 in. Screws, wood, G off current of Iron— Countersunk Round head Brass—   | secret, Beanla  uest, l  rade li  , Art.                 | brass  and's, Car Keen, and ist)—  No. 1                         | face,tland's N l Nettlef  | <br>iron w<br><br><br>Vo. 9052— | heels,            | 1/ 1/3 1/7 3/9 5/ 2/3 2/3 47½ 47½  | each  doz.  each  per cent.       | mouth.  Walter Scott,                                   | Greymouth.  " " " " " "                 |
| 322<br>323<br>329<br>330<br>335<br>336<br>338<br>339                      | Plugs and washe Round— 2 in Square— 2 in 2½ in. Pulleys, axle, Kenrick's- 1¾ in. 2 in Quadrants, iron, 16 in. 18 in. Screws, wood, G off current of Iron— Countersunk Round head Brass— Countersunk                                   | secret, Beanla uest, l rade li , Art.                    | brass     and's, Car   Keen, and  ist)—  No. 1  No. 1  No. 2     | face,tland's N l Nettlef  | <br>iron w<br><br><br>Vo. 9052— | heels,            | $1/$ $1/3$ $1/7$ $3/9$ $5/$ $2/3$ $2/3$ $47\frac{1}{2}$ $47\frac{1}{2}$ $27\frac{1}{2}$  | each  doz.  each  per cent.       | mouth.  Walter Scott,                                   | Greymouth.  " " " " " "                 |
| 322<br>323<br>329<br>330<br>335<br>336                                    | Plugs and washe Round— 2 in Square— 2 in 2½ in. Pulleys, axle, Kenrick's- ½ in. 2 in Quadrants, iron, 16 in. 18 in. Screws, wood, G off current of Iron— Countersunk Round head Brass— Countersunk Round head                         | secret,  Beanla  uest, larade li  , Art. , Art.          | brass  and's, Car  Keen, and ist)—  No. 1  No. 1A  No. 2  No. 2A | face, tland's N l Nettlef | <br>iron w<br><br><br>Vo. 9052— | heels,            | 1/ 1/3 1/7 3/9 5/ 2/3 2/3 47½ 47½  | each  doz.  each  per cent.       | mouth.  Walter Scott,                                   | Greymouth.  " " " " " " " " "           |
| 322<br>323<br>329<br>330<br>335<br>336<br>338<br>339<br>340<br>341        | Plugs and washe Round— 2 in Square— 2 in 2½ in. Pulleys, axle, Kenrick's- ½ in. 2 in Quadrants, iron, 16 in. 18 in. Screws, wood, G off current to Iron— Countersunk Round head Brass— Countersunk Round head Staples, lock, rin      | secret,  Beanla  uest, larade li  , Art. , Art.          | brass  and's, Car  Keen, and ist)—  No. 1  No. 1A  No. 2  No. 2A | face, tland's N l Nettlef | <br>iron w<br><br><br>Vo. 9052— | heels,            | $   \begin{array}{c}     1/3 \\     1/7 \\     \hline     3/9 \\     5/ \\     \hline     2/3 \\     2/3 \\     \hline     47\frac{1}{2} \\     47\frac{1}{2} \\     \hline     27\frac{1}{2} \\     \hline     27\frac{1}{2} \\   \end{array} $ | each  doz.  each  per cent.       | mouth.  Walter Scott,                                   | , Greymouth. "" "" "" "" "" "" "" "" "" |
| 322<br>323<br>329<br>330<br>335<br>336<br>338<br>339<br>340               | Plugs and washe Round— 2 in Square— 2 in 2½ in. Pulleys, axle, Kenrick's- ½ in. 2 in Quadrants, iron, 16 in. 18 in. Screws, wood, G off current of Iron— Countersunk Round head Brass— Countersunk Round head                         | secret,  Beanla  uest, larade li  , Art. , Art.          | brass  and's, Car  Keen, and ist)—  No. 1  No. 1A  No. 2  No. 2A | face, tland's N l Nettlef | <br>iron w<br><br><br>Vo. 9052— | heels,            | $1/$ $1/3$ $1/7$ $3/9$ $5/$ $2/3$ $2/3$ $47\frac{1}{2}$ $47\frac{1}{2}$ $27\frac{1}{2}$  | each  doz.  each  per cent.       | mouth.  Walter Scott,  ""  ""  ""  Forsyth and I        | , Greymouth. "" "" "" "" "" "" "" "" "" |
| 322<br>323<br>329<br>330<br>335<br>336<br>338<br>339<br>340<br>341<br>352 | Plugs and washe Round— 2 in Square— 2 in 2½ in. Pulleys, axle, Kenrick's- ½ in. 2 in Quadrants, iron, 16 in. 18 in. Screws, wood, G off current to Iron— Countersunk Round head Brass— Countersunk Round head Staples, lock, rin 6 in | secret,  Beanla  uest, larade li  , Art. , Art.          | brass  and's, Car  Keen, and ist)—  No. 1  No. 1A  No. 2  No. 2A | face, tland's N l Nettlef | <br>iron w<br><br><br>Vo. 9052— | heels,            | $1/$ $1/3$ $1/7$ $3/9$ $5/$ $2/3$ $2/3$ $47\frac{1}{2}$ $47\frac{1}{2}$ $27\frac{1}{2}$ $27\frac{1}{2}$ $9/$   | each  doz.  each  per cent.       | mouth.  Walter Scott,  ""  ""  ""  Forsyth and I mouth. | , Greymouth. "" "" "" "" "" "" "" "" "" |
| 322<br>323<br>329<br>330<br>335<br>336<br>338<br>339<br>340<br>341        | Plugs and washe Round— 2 in Square— 2 in 2½ in. Pulleys, axle, Kenrick's- ½ in. 2 in Quadrants, iron, 16 in. 18 in. Screws, wood, G off current to Iron— Countersunk Round head Brass— Countersunk Round head Staples, lock, rin      | secret,  Beanla  uest, larade li  , Art. , Art.          | brass  and's, Car  Keen, and ist)—  No. 1  No. 1A  No. 2  No. 2A | face, tland's N l Nettlef | <br>iron w<br><br><br>Vo. 9052— | heels,            | 1/ 1/3 1/7 3/9 5/ 2/3 2/3 2/3 47½ 47½ 27½ 9/ 11/   | each  doz.  each  per cent.       | mouth.  Walter Scott,  ""  ""  ""  Forsyth and I        | , Greymouth. "" "" "" "" "" "" "" "" "" |
| 322<br>323<br>329<br>330<br>335<br>336<br>338<br>339<br>340<br>341<br>352 | Plugs and washe Round— 2 in Square— 2 in 2½ in. Pulleys, axle, Kenrick's- ½ in. 2 in Quadrants, iron, 16 in. 18 in. Screws, wood, G off current to Iron— Countersunk Round head Brass— Countersunk Round head Staples, lock, rin 6 in | secret,  Beanla  uest, larade li  Art.  Art.  Art.  Art. | brass  and's, Car  Keen, and ist)—  No. 1  No. 1A  No. 2  No. 2A | face, tland's N l Nettlef | <br>iron w<br><br><br>Vo. 9052— | heels,            | $1/$ $1/3$ $1/7$ $3/9$ $5/$ $2/3$ $2/3$ $47\frac{1}{2}$ $47\frac{1}{2}$ $27\frac{1}{2}$ $27\frac{1}{2}$ $9/$   | each  doz.  each  per cent.  doz. | mouth.  Walter Scott,  ""  ""  ""  Forsyth and I mouth. | , Greymouth. "" "" "" "" "" "" "" "" "" |