

SCHEDULE 14.—PLUMBERS', ENGINEERS', AND LIGHTING MATERIAL—*continued.*

Item No.	Description.	Rate.	At per	Contractor.
Cocks, brass, <i>low-pressure</i> — <i>continued.</i>				
Draw-off, brass lever handles, screwed for iron—				
1313	$\frac{1}{2}$ in.	2/3	each	A. and T. Burt (Ltd.), Auckland.
1314	$\frac{3}{4}$ in.	3/6	"	Ditto.
1315	1 in.	5/3	"	"
Gas-main, plug or crutch-key, male and female—				
1316	$\frac{3}{8}$ in.	1/9	"	"
1317	$\frac{1}{2}$ in.	2/	"	"
1318	$\frac{3}{4}$ in.	3/	"	"
1319	1 in.	4/3	"	"
1320	$1\frac{1}{4}$ in.	8/	"	"
1321	$1\frac{1}{2}$ in.	11/	"	"
1322	2 in.	25/	"	"
Range, brass lever handles, 2 in. tails, with brass back nuts—				
1323	$\frac{3}{4}$ in.	5/3	"	"
1324	1 in.	7/6	"	"
Stop, crutch-key, female or male and female—				
1325	$\frac{1}{2}$ in.	2/9	"	"
1326	$\frac{3}{4}$ in.	4/	"	"
1327	1 in.	5/	"	"
Cocks, brass, <i>high-pressure</i> , heavy pattern—				
Ball, Doulton pattern—				
1328	$\frac{1}{2}$ in.	5/6	"	"
1329	$\frac{3}{4}$ in.	7/	"	"
1330	1 in.	10/6	"	"
Bib, screwed for iron, turned crutch-key—				
1331	$\frac{1}{2}$ in.	3/	"	"
1332	$\frac{3}{4}$ in.	4/	"	"
1333	1 in.	6/6	"	"
1334	$1\frac{1}{4}$ in.	19/	"	"
1335	$1\frac{1}{2}$ in.	22/6	"	"
1336	2 in.	60/	"	"
Bib, hose, screwed for iron, turned crutch-key, with cap and lining—				
1337	$\frac{1}{2}$ in.	3/9	"	"
1338	$\frac{3}{4}$ in.	5/	"	"
1339	1 in.	8/6	"	"
1340	$1\frac{1}{4}$ in.	22/6	"	"
1341	$1\frac{1}{2}$ in.	25/	"	"
1342	2 in.	60/	"	"
Stop, rough body, turned crutch-key, female ends—				
1343	$\frac{1}{2}$ in.	2/10	"	"
1344	$\frac{3}{4}$ in.	4/	"	"
1345	1 in.	6/	"	"
1346	$1\frac{1}{4}$ in.	19/	"	"
1347	$1\frac{1}{2}$ in.	22/6	"	"
Stop, polished body, turned crutch-key, female ends—				
1348	$\frac{1}{2}$ in.	3/6	"	Hardley's (Ltd.), Auckland
1349	$\frac{3}{4}$ in.	5/6	"	" "
1350	1 in.	8/6	"	" "
Stop, for showers, nickel-plated, marked "Hot" or "Cold," with long spindles and plates, female ends—				
1351	$\frac{1}{2}$ in.	5/6	"	A. and T. Burt (Ltd.), Auckland.