mean H.W. springs.]

Notice to Mariners No. 75 of 1926.

Marine Department, Wellington, N.Z., 7th December, 1926.

Number of Wellington Notice to Mariners incorrectly given. Number of Wettington Notice to Individual Notice to Individual Networks, TNFORMATION is hereby given that the notice to mariners relating to "River Thames, or Waiho (Waihou) River, Kirikiri bridge under construction," issued by the Marine Department, Wellington, New Zealand, on the 22nd October, 1926, and published in New Zealand Gazette No. 73 of 28th October, 1926, was incorrectly given as No. 62. The correct number of this notice is No. 63 of 1926, and this latter number will be used in any further reference to that notice. All existing conject of that notice should be altered to read

All existing copies of that notice should be altered to read No. 63 of 1926, accordingly.

G. C. GODFREY, Secretary.

Notice to Mariners No. 76 of 1926.

Marine Department,

Wellington, N.Z., 14th December, 1926. THE following notice to mariners, which has been received from the Hydrographer to the Admiralty, London, and the Department of Trade and Customs, Melbourne, is published for general information.

G. C. GODFREY, Secretary,

SOUTH PACIFIC OCEAN-ELLICE GROUP, FUNAFUTI ISLAND.

Fongafale Anchorage-Additional Information.

Position.—Observation spot + (Fongafale). Lat. 8° 31' S., long. 179° 13' E. (approx.). (1.) Beacons :— Positions—

- (a.) At a distance of about 6.08 cables 277° from observation spot +. (b.) At a distance of about 5.6 cables 254° from
- observation spot +. (c.) At a distance of about 7.1 cables 353° from
- observation spot +.

Details.—Beacons are to be inserted on the plan and chart in the above positions with the note "P.A." The following general caution is to be placed under the titles of the plan and chart and "Unreliable" shown against certain beacons

- (2.) Church : Position.-At a distance of 0.1 of a cable 180° from observation spot +
 - Details.—The symbol for a church is to be inserted on the plan of Fongafale anchorage in the above position.

(3.) Buoy established :---Position.--At a distance of about 8.7 cables 259¹/₂° from observation spot +.

Description.—A black bucy. Remarks.—It is to be marked "P.A." on the plan

and chart. (4.) Shoal marked by buoy :-- *Position.*--At a distance of about 6.0 cables 235° from

spot +

Depth.—1 $\frac{1}{2}$ fathoms (2^m7).

Remarks.—The shoal is marked by a black buoy; the notation "P.A." is to be inserted against it on the plan and chart. (Notice No. 1654 of 1926, dated 5th October.)

SOUTH PACIFIC OCEAN-FRIENDLY ISLANDS, TONGATÁBU.

Maria Bay-Non-existence of Leading-beacons.

Former Notice .--- No. 878 of 1926.

(a.) Rear beacon :--Position.--On Tufaka islet. Lat. 21° 04′ S., long. 175° 15' W. (approx.).

(b.) Front beacon :--Position.-About 94 cables north-westward of (a). Details.-Further information has been received that these two beacons are non-existent; they are to be expunged from the chart, together with the leading-line. (Notice No. 1771 of 1926, dated 23rd October.)

South Pacific Ocean-Gilbert Islands.

Nukunau (Byron Island)-Information re Position.

Position on chart .-- Centre of island, lat. 1° 23' S. long.

Position on chart.—Centre of Island, Iau. 1 20 5. 1006. 176° 26' E. (approx.). Details.—The position of Nukunau is reported to be in-correctly charted as indicated in the following note which is to be inserted against this island on the chart: Repd. to lie 3 miles to N.Ed. of charted position (1926). (Notice No. 1801 of 1926, dated 27th October.) [The astronomical positions are approximate unless seconds are given. The bearings are true and in degrees from 000°

(North) to 359° measured clockwise, and those relating to lights are from seaward. The visibility of lights is that in clear weather. Fog-signals are sounded only in thick or foggy weather. The elevation given is the height of focal plane above

TASMANIA-SOUTH COAST.

Maatsuyker Island Light-Power to be increased.

Mariners and others are hereby notified that the power of the Group - flashing White Light on Maatsuyker Island will be increased on or about 1st March, 1927. Position .- On south end of South-west islet. Lat. 43° 39' S.

 Long, 146° 18' E., on Chart No. 1079.
 Power.—The power will be increased to 239,000 candles.
 Note.—No further notice will be given. In other respect the light will remain unaltered.

Publication affected.—Admiralty List of Lights and Time Signals, Part VI, 1924, No. 2842.

Notice to Mariners No. 77 of 1926.

NEW ZEALAND .- NORTH ISLAND .- COOK STRAIT .- PORT NICHOLSON.

Marine Department, Wellington, N.Z., 15th December, 1926.

Submarine Telephone Cable laid and Notice Boards installed .--Former Cable discarded.

N OTICE is hereby given that a submarine telephone cable exists in a direction 130° from a position situated able exists in a direction 130° from a position situated 2,900 yards south-westward of Korokoro Stream, on the north-western shore of Port Nicholson, to a position on the western shore of Somes Island at 400 yards (approx.) from its northern extreme. The position of each end of the cable is marked on the shore by a post carrying a white equilateral triangular board, having sides 10 ft., bearing in black heavy type the word "Cable."

The foregoing is the only cable now in use between Somes Island and the shore; and the former cable, the existence which was not shown on Admiralty Plan No. 1423, has been abandoned.

Publications affected : Admiralty Plan No. 1423; "New Zealand Pilot," 9th edition, 1919; "New Zealand Nautical Almanac," 1927, page 246.

G. C. GODFREY, Secretary.

Notice to Mariners No. 78 of 1926.

NEW ZEALAND .- NORTH ISLAND .- NORTHERN COAST .--AUCKLAND HARBOUR.

Marine Department, Wellington, N.Z., 15th December, 1926.

Dredger operating off Western Tide-deflector.

THE Auckland Harbour Board notify that dredger "Hapai" is moored cardinally in a position 110° 550 ft. from the northern end of Western Tide-deflector, from which position the dredger will operate in a westerly and a south-westerly direction.

Publications affected: Admiralty Plan No. 1970; "New Zealand Pilot," 9th edition, 1919; "New Zealand Nautical Almanac," 1926, and "New Zealand Nautical Almanac," 1927.

G. C. GODFREY, Secretary.

Notice to Mariners No. 79 of 1926.

NEW ZEALAND .--- NORTH ISLAND .--- BAY OF PLENTY .---

TAURANGA HARBOUR. Marine Department, Wellington, N.Z., 15th December, 1926. Buoys installed.

THE Tauranga Harbour Board notify that the sailing-course from the junction of Kati-Kati Channel with Stella Channel at Sulphur Point Spit is now further marked by three additional black buoys placed in the following

Publications affected : Admiralty Plan No. 2521; "New Zealand Pilot," 9th edition, 1919, page 239 et seq.; "New Zealand Nautical Almanac," 1926, page 248; and 1927, page 226.

G. C. GODFREY, Secretary.