Notice to Mariners No. 27 of 1938.

Marine Department, Wellington, N.Z., 16th May, 1938.

NEW ZEALAND.—NORTH ISLAND.—WEST COAST. Manukau Bar

Previous Notice: No. 6 of 1938 hereby cancelled.

Position: Lat., 37° 03° S.; long., 174° 31′ E. (approx.).

Details: Visual observations taken from the Signal-station,
South Manukau Head, on the 10th May, 1938, indicate that
the main channel has re-formed in its old position with the
leading beacons and lights in line 074°. The channel is
approximately half a mile in width.

Chart affected: No. 2726.

Publications: New Zealand Pilot, 1930, page 58; New Zealand Nautical Almanac and Tide-tables, page 270.

Authority: Auckland Harbour Board, 11/5/38.

L. B. CAMPBELL, Secretary.

(M. 6/2/28.)

Notice to Mariners No. 28 of 1938.

Marine Department, Wellington, N.Z., 17th May, 1938.

NEW ZEALAND.—NORTH ISLAND.—HAURAKI GULF.

Kawau Bay: Prohibited Anchorage.

Position: Lat. 36° 26'·2 S.; long., 174° 46'·9 E. (approx.). Details: Anchorage is prohibited within the area enclosed by the following lines owing to the existence of a telegraph

- From a position 261° 5.4 cables from Fish Point, a line 046° 5.4 cables thence 088° to Kawau Island.
 From a position 242° 5.0 cables from Fish Point, a line 046° 5.0 cables thence 088° to Kawau Island.

Charts affected: Nos. 1998-3565-2543-1212. Publication: New Zealand Pilot, 1930, page 150.

L. B. CAMPBELL, Secretary.

(M. 4/3125.)

Notice to Mariners No. 29 of 1938.

Marine Department, Wellington, N.Z., 17th May, 1938.

NEW FORM OF TIME-SIGNALS.

Commencing on 1st June, 1938, the present form of timecommencing on 1st June, 1935, the present form of time-signals sent out from the Dominion Observatory through the National Broadcasting Service Stations 2YA and 3YA will be replaced by a signal consisting of six dots, separated by intervals of one second, the last dot being the exact minute. Each transmission will consist of a group of three signals at consecutive minutes, the times of transmission being as

follows :-

- (1) 10h. 28m.: 10h. 29m.: 10h. 30m. a.m., daily. (2) 3h. 28m.: 3h. 29m.: 3h. 30m. p.m., daily. (3) 7h. 28m.: 7h. 29m.: 7h. 30m. p.m., daily, except Sundays.
 (4) 10h. 28m.: 10h. 29m.: 10h. 30m. p.m., daily,

except Sundays.

The above times refer to New Zealand summer time during the period when summer time is in operation, and to New Zealand mean time when summer time is not in operation.

In all cases time-signals will be superimposed on the

The daily signals at 7.30 p.m. and 10.30 p.m., as well as those at 3.30 p.m. on Saturdays, Sundays, and holidays, are not under direct supervision at the Observatory, and consequently the errors of these signals are subject to rather greater variation than those of the signals which are sent under supervision. The errors of the signals sent under supervision seldom exceed a quarter of a second.

Publication affected: New Zealand Nautical Almanac and

Tide-tables, page 129.

Authority: Acting Director, Dominion Observatory, Authority:4/5/38.

L. B. CAMPBELL, Secretary.

(M. 25/255.)

Notice to Mariners No. 30 of 1938.

Marine Department, Wellington, N.Z., 17th May, 1938.

NEW ZEALAND.—SOUTH ISLAND.—WEST COAST.

(1) Breaksea Sound: Rock reported.

Details: Local fishermen report a submerged rock in the passage south-west of Entry Island. The area has not been examined. Position: Lat. 45° 36'·3 S.; long., 166° 42'·2 E. (approx.).

(2) Doubtful Inlet: Amended position of rock.

Position: Lat. 45° 18'.5 S.; long., 166° 53'.8 E. (approx.), Details: The sunken rock westward of the small island in Gaol Passage is reported to lie further south than charted. Vessels are advised to keep close to the southern shore of the

Passage.

Charts affected: Nos. 719—768—2589—1212.

Publication: New Zealand Pilot, 1930, pages 329 and 331.

Authority: Hydrographic Report, Appendix No. 3 to
Report of Proceedings, "Leiths?" No. 29 of 8/4/1938.

L. B. CAMPBELL, Secretary.

(M. 6/2/55.)

Notice to Mariners No. 31 of 1938.

Marine Department, Wellington, N.Z., 17th May, 1938.

NEW ZEALAND,-NORTH ISLAND,-HAURAKI GULF.

Ponui Passage Light: Temporary Light to be exhibited.

Position: Lat. 36° 54′·0 S.; long., 175° 10′·9 E. (approx.). Details: On 1st June, 1938, the light will be extinguished and a temporary light of the ordinary masthead oil lamp type, fixed at a relatively low level, of lesser arc and generally of limited visibility will be exhibited. Further notice will be given when the reconstruction of the main light has been

Charts affected: Nos. 1896—2543—1212.
Publications: New Zealand Pilot, 1930, page 165; New Zealand Nautical Almanac and Tide-tables, page 157, No. 21.

L. B. CAMPBELL, Secretary.

(M. 8/9/96.)

The Industrial Conciliation and Arbitration Act, 1925.— Notice of Cancellation of Registration.

Department of Labour Wellington, 18th May, 1938.

NOTICE is hereby given that the registration of the North Island Timber Workers' Industrial Association of Workers, registered number 1460, situated at Wellington, is hereby cancelled as from the date of the publication of this notice in the Gazette.

G. M. F. JACKSON, Deputy Registrar of Industrial Unions.

The Sharebrokers Act, 1908.—Licensed Sharebrokers for the Year 1938.

Office of Commissioner of Stamp Duties, Wellington, 12th May, 1938.

T is notified that licenses under section 4 of the Sharebrokers Act, 1908, to carry on the business of share-broking in the Dominion of New Zealand for the current calendar year have been issued to the undermentioned persons.

P. G. PEARCE, Commissioner of Stamp Duties.

	AUCKLAND DISTRICT.			
Allen, H				Auckland.
Baker, E. T.				Tauranga.
Battersby, J. H.				Auckland.
Bell, G				* **
Bowker, W. W.				,,
Brickell, H. A.				,,
Buddle, B. D.		• •	• •	,,
Buddle, F. C.				,,
Bull, E				,,
Buttle, G. R.				,,
Buttle, K. N.				,,